

Oil Field Environmental Incident Summary

Incident: 20150306093038 **Date/Time of Notice:** 03/06/2015 09:30

Responsible Party: BERENERGY CORPORATION

Well Operator: BERENERGY CORPORATION

Well Name: AMANDA KUNKEL 3

Field Name: GLENBURN

Well File #: 2662

Date Incident: 3/4/2015 **Time Incident:** 07:00

Facility ID Number:

County: RENVILLE

Twp: 158 **Rng:** 82 **Sec:** 1 **Qtr:** NE NW

Location Description: leak in the underground flowline for the Kunkel 3 well occurred apx. 250' E of the Kunkel 2 well located in the NENW of Sec. 1, T158N-R82W in Renville County. The topsoil was impacted in an area 8' wide by 225' long running to the SW.

Submitted By: William Braden

Received By:

Contact Person: William Braden
7114 W JEFFERSON AVE STE 206
LAKEWOOD, CO 80235

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1025 Feet

Distance Nearest Water Well: 1.2 Mile

Type of Incident Pipeline Leak

Release Contained in Dike No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

8' by 225'

Potential Environmental Impacts:

Salt impacted soil

Action Taken or Planned:

Impacted soil piled up, will be hauled to a proper disposal starting today. Good topsoil will be returned to the spill site per the direction of the surface landowner. The pipeline leak will be excavated and the line inspected for cause of the leak and the line's condition. The bad portion of the line will be cut out and a new piece welded in place. Any impacted soil around the leak site will be excavated and replaced also.

Wastes Disposal Location: The Prairie Disposal LLC landfill in Tioga and the Clean Harbors landfill in Sawyer

Agencies Involved:

Updates

Date: 3/6/2015 **Status:** Reviewed; Followup Required **Staff:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.